

HAB5  
ARIZ  
10-TUCSO,  
32D-

## HISTORIC AMERICAN BUILDING SURVEY

### INDEX TO PHOTOGRAPHS

Tucson Plant Materials Center, Superintendent's Cottage (Bldg. No. 8)    HABS No. AZ-159-D  
3241 North Romero Road  
Tucson  
Pima County  
Arizona

Jim Woodward, Photographer      December 1993      (AZ-159-D-1 through AZ-159-D-7)

- AZ-159-D-1      SUPERINTENDENT'S COTTAGE NORTH FRONT,  
LOOKING SOUTH.
- AZ-159-D-2      SUPERINTENDENT'S COTTAGE NORTH FRONT AND EAST  
WALL, LOOKING SOUTHWEST. SUPERINTENDENT'S GARAGE  
(BLDG. NO. 9) AT FAR RIGHT.
- AZ-159-D-3      SUPERINTENDENT'S COTTAGE NORTH FRONT AND EAST WALL  
SHOWING WOOD FRAME ADDITION.
- AZ-159-D-4      SUPERINTENDENT'S COTTAGE EAST AND SOUTH WALLS,  
LOOKING NORTHWEST.
- AZ-159-D-5      SUPERINTENDENT'S COTTAGE WEST WALL AND NORTH  
FRONT SHOWING CONCRETE BLOCK UTILITY ROOM  
ADDITION.
- AZ-159-D-6      SUPERINTENDENT'S COTTAGE PORTION OF EAST WALL SHOW-  
ING TYPICAL STEEL SASH CASEMENT WINDOW AND LOG  
VIGAS.
- AZ-159-D-7      SUPERINTENDENT'S COTTAGE INTERIOR, NORTH WALL OF  
KITCHEN SHOWING BUILT-IN CABINETS.

Note: For photocopies of historic photographs showing contextual views of the site, see photographs for Tucson Plant Materials Center, HABS No. AZ-159.

Note: For additional written descriptive information, see narrative report for Tucson Plant Materials Center, HABS No. AZ-159.